INSTALLATION INSTRUCTIONS RISE® SEALING SYSTEM FOR MULTI-CABLE TRANSITS



TESTED TO IMO RESOLUTION A.754(I8);
FIRE CLASS AO-A60 and HO-HI2O
EC (MED) CERTIFICATE
O9I56/CO ISSUED BY BUREAU VERITAS





PLEASE ALSO REFER TO THE STAMPED INSTALLATION DRAWINGS ATTACHED TO OUR MED AND TYPE APPROVAL CERTIFICATES

Copyright : BEELE Engineering BV/CSD International BV, Aalten, the Netherlands.

Proprietary rights on all drawings and technical data released in this brochure.

© 1997-2010

Edition : September 2010

Note : No part of this publication may be reproduced without explicit written approval of

BEELE Engineering BV.

Research & Development : BEELE Engineering BV, Aalten, the Netherlands.

Note : The manufacturer reserves the right to make dimensional and design modifications

without prior notification.

® : ACTIFIRE, ACTIFOAM, AQUASTOP, BEEBLOCK, BEELE, BEESEAL, CONDUCTON, CRUSHER, CSD,

CSD THE SIMPLE SEAL SYSTEM, DRIFIL, DYNATITE, FIRSTO, FIWA, LEAXEAL, MULTI-ALL-MIX, NOFIRNO, profiles NOFIRNO gaskets, RAPID TRANSIT SYSTEM, RIACNOF, RISE, RISWAT, \$, SLIPSIL, flanges SLIPSIL plugs, ULEPSI and YFESTOS are registered trade marks of BEELE Engineering BV.


brochure code : rise cable/installation/en/mar











RISE®	cable		sleeve	article
cable sleeve	diameter		length	number
12/6 14/8	5 - 7 7 - 9		140 140	80.0051 80.0052
16/10	9 - 11		140	80.0053
18/12	11 - 13	μ	140	80.0054
20/14	13 - 15	all dimensions in mm	140	80.0055
22/16	15 - 17	ns ii	140	80.0056
27/19	17 - 21 21 - 25	oisı	140	80.0057
31/23 35/27	21 - 25 25 - 29	ime	140 140	80.0058 80.0059
39/31	29 - 33	all d	140	80.0060
46/36	33 - 39		140	80.0061
52/42	39 - 45		140	80.0062
58/48	45 - 51		140	80.0063
64/54	51 - 57		140	80.0064
70/60	57 - 63		140	80.0065
12/6	5 - 7		160	80.0100
14/8	7 - 9		160	80.0101
16/10	9 - 11		160	80.0102
18/12	11 - 13	4	160	80.0103
20/14 22/16	13 - 15 15 - 17	all dimensions in mm	160 160	80.0104 80.0105
27/19	17 - 21	ins i	160	80.0106
31/23	21 - 25	nsio	160	80.0107
35/27	25 - 29	lime	160	80.0108
39/31	29 - 33	allc	160	80.0109
46/36	33 - 39		160	80.0110
52/42	39 - 45		160	80.0111
58/48	45 - 51		160	80.0112
64/54	51 - 57		160	80.0113
70/60	57 - 63		160	80.0114
12/6	5 - 7		210	80.0200
14/8	7-9		210	80.0201
16/10 18/12	9 - 11 11 - 13		210 210	80.0202 80.0203
20/14	13 - 15	ш	210	80.0203
22/16	15 - 17	in	210	80.0205
27/19	17 - 21	ons	210	80.0206
31/23	21 - 25	ensi	210	80.0207
35/27	25 - 29	all dimensions in mm	210	80.0208
39/31	29 - 33	all	210	80.0209
46/36	33 - 39		210	80.0210
52/42	39 - 45		210	80.0211
58/48	45 - 51		210	80.0212
64/54	51 - 57		210	80.0213
70/60	57 - 63		210	80.0214

RISE®		sleeve	article
filler sleeve		length	number
18/12 single 18/12 multi 18/12 single 18/12 multi 18/12 single 18/12 multi 27/19 single 27/19 multi 27/19 single 27/19 multi		140 140 160 160 210 210 140 140 160	80.0323 80.0324 80.0313 80.0314 80.0303 80.0304 80.0326 80.0327 80.0316 80.0317
27/19 single	all dimensions in mm	210	80.0306
27/19 multi		210	80.0307

1






PRODUCT INFORMATION SEALANT

01) dark grey $1.30 \pm 0.03 \text{ g/cm}^3$ 02) specific gravity 03) 0.5 - 1 hour depending on curing of top layer temperature and air humidity service temperature -50 °C up to +160 °C 04) 1.15 MPa 05) tensile strength 125% 06) elongation at break 07) hardness 35 Shore A 08) elastic deformation approx. 25% UV, Ozone, arctic conditions 09) resistance more than 20 years 10) ageing supplied in 310 ml cartridges 11) 12) storage to be stored cool and dry min/max temperature =

> +5/+30° C guaranteed 6 months; when applied later than 6 months after date of manufacturing, curing and adhesive properties have to be checked before application



FIWA® is absolutely HALO-GEN FREE (tested according to Naval Engineering Standard NES 713: Issue 3). Furthermore FIWA® has a low smoke index (NES 711: Issue 2: 1981) and a high oxygen index (ISO 4589-2: 1996), and low flame spread characteristics according to IMO Resolution A.653(16).

Shelf life is 12 months when stored properly. Since we have no control on storage, we can only guarantee for 6 months.

PRODUCT INFORMATION PUTTY

01) colour black 02) specific gravity

03) curing of top layer

04) service temperature -50 °C up to +160 °C

05) tensile strength 0.80 MPa

06) elongation at break

07) hardness (80 elastic deformation

09) electrical resistance 10) ageing

supplied in 11) 12) storage

13)

storage life

storage life

13)

1.30 ± 0.03 g/cm³

0.5 - 1 hour depending on temperature and air humidity

40% 35 Shore A

approx. 25% < 100 Ω

more than 20 years 310 ml cartridges to be stored cool and dry min/max temperature =

+5/+30° C

guaranteed 6 months; when applied later than 6 months after date of manufacturing, curing

and adhesive properties have to be checked before application



CONDUCTON® putty is an electrically conductive sealing putty based on a single component silicone compound.

CONDUCTON® has been developed for the RISE/EMC multi-cable and pipe transits.

Shelf life is 12 months when stored properly. Since we have no control on storage, we can only guarantee for 6 months.



CONDUCTON® flexible rubber has been developed for the RISE®/EMC multi-cable transits and is used to fill the cavity around the ducted cables in the conduit sleeve, instead of making use of the putty. This rubber can be molded by hand and offers the highest attenuation.

CONDUCTON® flexible rubber is absolutely HALOGEN FREE and has a toxicity index of 0,00 (tested according to Naval Engineering Standard NES 713: Issue 3).


Furthermore CONDUCTON® has a low smoke index (NES 711: Issue 2: 1981), an oxygen index of 38,2% (ISO 4589-2: 1996), and a temperature index of 294 °C (ISO 4589-3: 1996).

CONDUCTON® flexible rubber fullfils the criteria for use on board of UK Navy vessels for EMP/EMI penetrations.






1) The cables can be ducted through the conduit sleeve/ frame in random order. It is most important that they are not pulled too tight so as not to hamper their separation when RISE® insert sleeves are inserted.





2) After the cables have been ducted, RISE® insert sleeves are applied around each cable.

The insert sleeves are split lengthwise and can therefore be placed around the cables in front of the conduit.











3) The remaining free space in the conduit is filled with RISE® filler sleeves type 27/19 and 18/12. For ease of filling, the RISE® filler sleeves are supplied non-split. The ratio 27/19 to 18/12 should be about 2:1.





4) Push the insert/filler sleeves into the conduit in such a way as to leave about 20 mm free space at the front and the back. The whole set of filler sleeves should fit tightly into the conduit to provide sufficient mechanical stability.










5) A 20 mm thick layer of FIWA® sealant is applied at each side of the conduit. Clean and dry the conduit opening and the cables thoroughly, and remove any dirt, rust or oil residues before applying the sealant.





6) The conduit should be overfilled with FIWA® sealant, because some sealant will be pushed between and into the empty filler sleeves during further finishing. This will contribute to obtain higher tightness ratings.









7) To smooth the surface of the FIWA® sealant layer, a cloth is sprayed with water. This prevents the sealant from sticking to the cloth. Note: do not use soap water!





8) The cloth is then used to press down the sealant layer.

People with sensitive skin should use gloves when working with FIWA®. Please refer to the Safety Data Sheet for more information.









9) The FIWA® sealant between the cables is pressed down and smoothed by hand or with a spatula or putty knife.

This is essential to obtain optimum gas and water tightness.





10) The surface can be smoothed by hand. Just wet the hands thoroughly with soap and water. No dirty hands when working with FIWA® and a very neat surface is the result.











11) After smoothing is finished, a last check should be taken to ensure sufficient sealant has been applied in between the cables (especially for transits with larger amounts of cables). This is most important for water and gas tight penetrations.





12) For A-class penetrations (which are insulated), the conduit sleeve/frame needs to be insulated only at the insulated side of the bulkhead or at the lower side of the deck.

No extra insulation needed in front of the penetration and/or in between the cables.











13) To prevent the filler sleeves from falling out of the conduit sleeve/frame, they are squeezed together to form a compact bundle. They are available in bundles of ten pieces.





14) The optimized viscosity and the superb adhesion properties of the FIWA® sealant make applying the sealant overhead an easy matter. FIWA® sealant does not sag and will not drip off.










15) The RISE cable penetrations are certified for ducting bundles of cables.


Pull a set of bundled cables through the conduit and place a RISE® insert sleeve around the cable.





16) Push the insert/filler sleeves into the conduit in such a way as to leave about 20 mm free space at the front and the back. The whole set of filler sleeves should fit tightly into the conduit to provide sufficient mechanical stability.

The conduit to be finished as described on pages 5-8.











1) Adding extra cables is an easy job. Cut away the sealant layer at both sides of the penetration with a knife or a hollow punch in a tapering shape. This creates a good foundation for the sealant mass to be applied later.





2) Pull the cable through one of the empty filler sleeves with an inner diameter more or less corresponding to the outer diameter of the cable. If the empty filler sleeves are not fitting to the size of the cable to be ducted, a number of these insert sleeves must be removed from the penetration.










3) Place a RISE® sleeve around the newly ducted cable. Push the insert sleeve into the conduit. Fill open spaces with RISE® filler sleeves.





4) Refill the opening in the sealant layer at both sides of the penetration with sufficient FIWA® sealant. The FIWA® sealant is pressed down firmly and smoothed with a damped cloth.

Note: do not use soap water!



